# KHM

## KING'S HARBOUR MASTER PLYMOUTH

### **NAVWARN No 002/23**

### PLYMNAVWARN 002 LONGROOM CAMBER - HAZARD

### PLYMNAVWARN 002/23

### **ISSUED 1 JANUARY 2023**

### BY LONGROOM PORT CONTROL

### **LONGROOM CAMBER - HAZARD**

- 1. DAMAGE HAS BEEN SUSTAINED TO THE SEAWALL WITHIN LONGROOM CAMBER, PLYMOUTH SOUND (50°21.771'N, 004°9.344'W). A WHITE BOOM AND VERTICAL CHAIN HAS BEEN INSTALLED, EXTENDING APPROXIMATELY 4M FROM THE COPE EDGE, IN ORDER TO KEEP VESSELS AT A SAFE DISTANCE FROM THE WALL
- 2. MARINERS ARE ADVISED TO NAVIGATE WITH CAUTION IN THE AREA
- 3. CANCEL PLYMNAVWARN 002/22
- 4. PLYMNAVWARNS IN FORCE: 001 & 002/23

Sunday 01 Jan 2023

R Giles King's Harbour Master, Plymouth