



KING'S HARBOUR MASTER CLYDE

LNTM No 08/17

ALTERATION OF AID TO NAVIGATION (A4411.6) LOCH GOIL THE PERCH FRONT

BA Chart 3746

- 1) Mariners are advised that GSS workboat 'Mary M' will begin work on the 19th January 2017 to alter aid to navigation (A4411.6) Loch Goil Leading Light 318deg. The Perch Front in position 56°06.913'N 004°54.293'W. This will involve the installation of a new port entry light.
- 2) During this time the light should be considered unreliable and mariners should navigate with caution when transiting the area.
- 3) Further notice and information will be provided on completion of the installation.
- 4) CWM 5/17 is now cancelled.
- 5) Further Information can be obtained from QHM Harbour Control on VHF CH73 or 01436 674321 extn 3555/4005.
- 6) Next CWM 09/17

Wednesday 18 Jan 2017

David Lightfoot OBE MSM AFNI
Queen's Harbour Master Clyde