



KING'S HARBOUR MASTER PLYMOUTH

NAVWARN No 018/23

PLYMNAVWARN 018 WHIDBEY BEACON - UPDATE

PLYMNAVWARN 018/23

ISSUED 02 AUGUST 2023

BY LONGROOM PORT CONTROL

PLYMNAVWARN 018/23 WHIDBEY BEACON - UPDATE (PLYMOUTH SOUND)

1. WHIDBEY DIRECTIONAL BEACON IS CURRENTLY UNRELIABLE (POSITION 50° 19.53' N 004° 07.27' W)
2. MARINERS ARE ADVISED ACCORDINGLY
3. THIS PLYMNAVWARN CANCELS AND SUPERSEDES PLYMNAVWARN 017/23
4. PLYMNAVWARNS IN FORCE 001 – 003 & 018/23

Wednesday 02 Aug 2023

R Giles
King's Harbour Master, Plymouth