



## KING'S HARBOUR MASTER PORTSMOUTH

### NAVWARN No 27/14

#### Shoal patches off Fountain Lake Jetty

1. MARINERS ARE ADVISED THAT DEPTHS IN THE 6.0M CHARTED AREA CLOSE IN TO THE EASTERN END OF FOUNTAIN LAKE JETTY BERTHS 3 AND 4 HAVE BEEN REPORTED AS HAVING A MINIMUM DEPTH OF 5.4M FOLLOWING A RECENT SURVEY.
2. QHM PORTSMOUTH WILL ONLY BERTH SHIPS OF AN APPROPRIATE DRAFT IN THIS AREA AND USE OF WIDE BERTHING CATAMARANS WILL CONTINUE.
3. UKHO WILL ISSUE AN NTM IN DUE COURSE.
4. THE FOLLOWING PORTSMOUTH NAVWARNS REMAIN IN FORCE: 24/14, 23/14, 22/14, 21/14, 13/14, 69/13, 67/13, 65/13, 62/13, 39/13, 29/13, 57/12, 52/11, 40/11, 45/10, 78/05, 10/04.

Queen's Harbour Master